

Problem – TA620 rev5

Revision 5 EPROMS are hard coded to observe only the old Daylight Saving rules.

Resolutions:

1. Manually Change Time

You will need to download and install the latest Microsoft Update that corresponds with your operating system to have access to the new DST schedule prior to March 4, 2007. You can find the update at <http://www.microsoft.com/windows/timezone/dst2007.msp>.

- Genesis Pro, TA100 Pro - need to set up an Auto Process that will change the time clocks right after the computer time changes. For more information visit our website at: <http://www.expresstimesystems.com/dst.htm>.
- TA50 Pro – need to manually poll your time clock with the polling option to “Set Clock date and time” box checked. *Check to make sure the Time on your computer is correct prior to polling. For more information visit our website at: <http://www.expresstimesystems.com/dst.htm>.

2. Replace TA620 rev5 with a New 2007 compliant Time Clock (We are offering a \$200 trade-in allowance for working TA620 rev5 time clocks towards the purchase of a new one)

- TA620 rev6 clocks are soft coded to accept dates from the software.
- HandPunch Biometric series are soft coded to accept dates from the software.
- TA7000 series are soft coded to accept dates from the software.

Look at the examples below to determine if you have a rev5 or rev6 TA620 time clock.

Below left is a TA620 rev5 display. Notice that the day of the week, date, and time appears only on one line.



Below right is a TA620 rev6 display. Notice that the time is larger and covers two lines. The day, date, month, and year fields are on the right side.

